


KIA PICANTO 2004 - ...

	D(H)	S()	T()	C()
K105-A	5,6	75	1350	1000
D = g* TC/T+C ()		
S -				
T-				
C -				



1.	2.	K105-A	1
,	,	50	1
,	,	14	1

3.	4.	1.	1.
,	,	(7) (8) 12 1.25 35	12 35.

1 (L/1)	2 (54/2G)	3 (31/3)	4 (R/4)	5 (58R/5)	6 (54/6)	7 (58L/7)




Схема сборки К105-А

ПОЗ.	НАИМЕНОВАНИЕ	К-ВО
1	Баика ТСУ	1
2	Кронштейн левый	1
3	Кронштейн правый	1
4	Прокладка шара	2
5	Подрозетник тип А	1
6	Шар	1
7	Болт M12x1.25x35	4
8	Болт M12x35	4
9	Болт M12x90	2
10	Гайка M12(с.контр.)	4
11	Гровер d 12	6
12	Шайба d 12	11

